




DANGER



SILICA DUST HAZARD

Inhalation of respirable crystalline silica dust that may occur during stone cutting and fabricating can cause severe illness, cancer or death

Always use Personal Protective Equipment (PPE) such as NIOSH certified air supplied respirators

WET cutting, milling, drilling, or polishing ONLY

Always cut, drill, polish, or mill in well ventilated areas

WET clean up ONLY

Remove and wash work clothes on your work site

Always make sure all OSHA & NIOSH standards and regulations are strictly followed

La inhalación de polvo respirable de sílice cristalina que puede generarse durante el corte y la fabricación de piedra puede causar enfermedades graves, cáncer o la muerte

Utilice siempre Equipo de Protección Personal (EPP), como respiradores con suministro de aire certificados por NIOSH

Realice ÚNICAMENTE cortes, fresado, perforación o pulido en húmedo

Corte, perfore, pula o frese siempre en áreas bien ventiladas

Realice la limpieza ÚNICAMENTE con métodos húmedos Quítese y lave la ropa de trabajo en el lugar de trabajo

Asegúrese siempre de que se cumplan estrictamente todas las normas y reglamentos de OSHA y NIOSH

For more details:
OSHA/NIOSH Worker Exposure to Silica at
www.cdc.gov/niosh/docs/2026-101/pdfs/2026-101.pdf

Scan QR Code for more Silica Safety & Health Awareness



gfostone.com/safety



California
Prop 65



www.gfostone.com